




Case History



Date
July 2006 & May 2008

Customer
MoD IPT

Location
Plymouth

Product Used
VpCI 609

City Road Business Centre
City Road,
Derby, DE1 1TJ

Tel: +44 (0)1332 347175
Fax: +44 (0)1332 347185
Email: enquiries@hitektechnologysolutions.co.uk
www.hitektechnologysolutions.co.uk

Warship Blister Tanks

Background

Blister tanks are two void spaces that were fitted on either side of a Naval Warship post manufacture.

These void spaces are subject to two inspections per year by Lloyds.

Due to the way these tanks had been fitted, a lot of moisture was in the air resulting in corrosion. Lloyds were concerned about the amount of corrosion appearing inside the void spaces.

HITEK-nology Solutions Ltd was approached by an MoD IPT to provide a solution.

Treatment chosen

VpCI 609 is fogged into the internal volume of the voids resulting in a low cost two years anti-corrosion protection.

HSL were requested to retreat the Blister Tanks again in June 2008, on the left is a picture of the sacrificial plates placed in the Tanks in 2006, as can be seen two years protection was achieved.